






MACHINE



FUSE 1.6A@ 500V 6x32



MAINS SWITCH



CN1

